



ASIA TURBOMACHINERY & PUMP SYMPOSIUM  
SINGAPORE | 22 – 25 FEBRUARY 2016  
M A R I N A B A Y S A N D S




# NATIONAL FERTILIZERS LIMITED, NANGAL UNIT





ASIA TURBOMACHINERY & PUMP SYMPOSIUM  
SINGAPORE | 22 – 25 FEBRUARY 2016  
M A R I N A B A Y S A N D S



# REVAMP OF STEAM TURBINE FOR SYNTHESIS GAS COMPRESSOR AT NFL NANGAL

By:  
Rakesh Markan  
Deputy General Manager(Mech)  
NFL Nangal

## BOIGRAPHY:

Rakesh Markan

### Graduate in Mechanical Engineering


- Nearly 30 Years of Experience in Maintenance, Troubleshooting and Major Overhaul of Steam Turbines and Centrifugal Compressors, Erection and preventive maintenance of connected Steam and Process Gas Piping in Fertilizer Industry.
- Worked in Ammonia Plant- Shell Gasification Process, Ammonia Plant-SMR Process, Urea Plant and Boiler Plants at various positions.
- Worked in Various organizations in Fertilizer Sector, besides the four Units of National Fertilizers Limited, for trouble shooting and subsequent maintenance of high speed rotating machines,.
- Presented papers, on case studies related to reliability maintenance/Improvement in productivity, at various forums in India
- Hands on experience in planning and execution of major turnarounds of Fertilizer Plants.
- At present holds the position as Chief Manager (Mechanical) in Nangal Unit of National Fertilizers Limited.



# ABSTRACT:

National Fertilizers Limited, Nangal Unit, India had under taken the revamp of Steam Turbine of Synthesis Gas Compressor in January 2014. The plant startup, after machine revamp, was delayed by 40 days, because of various activities related to machine revamp which were not envisaged before commencement of the revamp. This paper throws light on those unforeseen jobs which lead to delay in startup and the lessons learnt to avoid such delays in future.

# SYNTHESIS GAS COMPRESSOR, NFL NANGAL



## **MAJOR JOBS SCHEDULED TO BE CARRIED-OUT DURING REVAMP**

- Replacement of Rotor with New High Efficiency one
- Replacement of Nozzle Segment with High Efficiency one
- Replacement of guide blade carrier with New High Efficiency one
- Replacement of Steam Glands
- Replacement of Steam Control Valves with Modified ones




# MAJOR JOBS SCHEDULED TO BE CARRIED OUT DURING REVAMP

## REPLACEMENT OF ROTOR AND GUIDE BLADE CARRIER



# REPLACEMENT OF STEAM INLET NOZZLES






# MAJOR JOBS SCHEDULED TO BE CARRIED-OUT DURING REVAMP

## REPLACEMENT OF STEAM GLANDS





# REPLACEMENT OF STEAM CONTROL VALVES' ASSEMBLY





***TIME AS PER ORIGINAL SCHEDULE : 27 DAYS***

***ACTUAL TIME TAKEN: 67 DAYS***

**MAJOR ACTIVITIES INVOLVED IN MACHINE OVERHAUL AS PER NORMAL PRACTICE**

OPEN TOP CASING

DISMANTLING THE BEARINGS

REMOVE ROTOR,STEAM GLANDS,GUIDE BLADE CARRIERS,NOZZLE BLOCK

CLEANING OF CASING AND PLACE NEW BEARINGS

CENTRING OF NEW NOZZLE BLOCK

CENTRING OF NEW ROTOR WITH TURBINE CASING AND BEARING PEDESTALS

INSTALL NEW NOZZLE BLOCK,CENTRING OF NEW NOZZLE BLOCK WITH ROTOR AND  
TURBINE CASING

# **MAJOR ACTIVITIES INVOLVED IN MACHINE OVERHAUL AS PER NORMAL PRACTICE**

INSTALL NEW STEAM GLANDS, CENTRING OF GLANDS w.r.t ROTOR AND TURBINE CASING

INSTALL NEW GUIDE BLADE CARRIER, CENTRING OF NEW GUIDE BLADE CARRIER w.r.t TURBINE CASING AND ROTORBOXUP TOP CASING COVER.

ALIGNMENT OF TURBINE WITH DOWNSTREAM MACHINE.



- NUMEROUS HIGH PRECISION MACHINING JOBS CAME UP DURING JOB EXECUTION, WHICH WERE NOT ANTICIPATED BEFORE COMMENCEMENT OF REVAMP.
- ***THESE JOBS WERE NOT COVERED IN THE ORIGINAL SCHEDULE*** BUT THE SAME WERE EXECUTED AND PLAYED A MAJOR ROLE IN EXTENDING THE SCHEDULED TIME

# ACTIVITIES WHICH LEAD TO DELAY IN EXECUTION

AS PER AGREEMENT BETWEEN OEMs & CUSTOMER ALL THE NEW REDESIGNED PARTS SHALL BE WITH IMPROVED EFFICIENCY BUT INTERCHANGEABLE WITH THE ONES ORIGINALLY INSTALLED.

JOURNAL DIAMETER OF THE NEW ROTOR WAS 124.83 MM AGAINST THE ORIGINAL ONE AS 119.82MM.

DESIGN OF BEARINGS WAS CHANGED TO TILTING PAD TYPE INPLACE OF BUSH TYPE.



150mm  $\phi$



260mm  $\phi$



# MODIFICATION OF SEATING AREAS OF FRONT END BEARING PEDESTAL

BEFORE  
MACHINING


AFTER  
MACHINING



Packing  
Plates

# HIGH PRECISION MACHINED COMPONENTS FABRICATED IN LOCAL W/S




## Centering keys for Parallel alignment of Turbine Casing with Bearing Pedestal





# HIGH PRECISION MACHINED COMPONENTS FABRICATED IN LOCAL W/S

## MAIN AXIAL KEY UNDER FRONT BRG PEDESTAL




**DELAY DUE TO WRONG SEALING ANGLE OF THE OF SEAL RING ON  
EMERGENCY STOP VALVE 25 DEG. INSTEAD OF 15 DEG.**






**FIXTURES FOR MACHINING OF STEAM GLANDS WERE MADE TO  
ACCOMMODATE THE NEW STEAM GLANDS ON LATHE MACHINES IN  
NFL WORKSHOP**





# **JOBS SUBSEQUENT TO THE VISIT OF FACT FINDER DEPUTED BY THE OEMs**





# **JOBS SUBSEQUENT TO THE VISIT OF FACT FINDER**

## **DEPUTED BY THE OEMs**



# REMOVAL OF DAMAGED STUDS IN TOP CASING





# REPLACEMENT OF STRAINERS IN THE MAIN STEAM INLET LINES. THE JOB REMAINED HELD UP DUE TO NON AVAILABILITY OF SPARE STRAINERS





# REPLACEMENT OF ALL OLD DAMAGED STUDS INSTALLED IN THE BOTTOM CASING

BROKEN BOLTS/STUDS IN THE  
BOTTOM CASING



# BOTTOM CASING AFTER REMOVAL OF NOZZLE BLOCK AND GUIDE BLADE CARRIER

NOZZLE BLOCK






# SHIFTING OF BOTTOM CASING TO MECHANICAL WORKSHOP FOR REMOVAL OF CENTER GUIDE KEYS & ECCENTRIC BUSHES



CENTRE  
GUIDE KEYS

**BASIC REFERENCES OF BOTTOM CASING W.R.T  
FOUNDATION AND BEARING PEDESTALS LOST**

# REMOVAL OF CENTRE GUIDE KEYS IN MECHANICAL WORKSHOP









# REMOVAL OF ECCENTRIC BUSH FOR NOZZLE BLOCK IN MECHANICAL WORKSHOP





# SPRING SUPPORTS WERE FOUND BADLY RUSTED AND FEW WERE FOUND DAMAGED



Upper position




Midposition



Lower position




# MISALIGNMENT OF STEAM INLET FLANGES




# **CORRECTION OF PIPING MISALIGNMENT BY CUTTING AND REWELDING THE HIGH PRESSURE/HIGH TEMPERATURE STEAM PIPING**

## Welding Joints cut and Pipe relocated






# MISALIGNMENT OF STEAM INLET FLANGES



S. No.	Description	Main Steam Flange(Left)		Main Steam Flange (Right)	
		Before Correction	After Correction	Before Correction	After Correction
1	Parallel Misalignment, in mm	50	2	45	2.5
2	Angular Misalignment, In mm	3.85	0.10	2.30	0.10

# Provision of Key Phasor





TEMPORARY STRAINERS WERE INSTALLED IN THE  
OIL PIPING FOR CLEANING OF LUBE OIL



# DELAY ANALYSIS

- ❖ MACHINING OF BEARING PEDESTALS
- ❖ MACHINING OF L-RING SEATING AREAS IN TOP CASING
- ❖ REPLACEMENT OF CONTROL VALVE SEATS IN TOP CASING
- ❖ REMOVAL OF OLD STUDS AND FIXING OF NEW ONES
- ❖ FABRICATION OF HIGH PRECISION KEYS, LEVELLING PLATES, FIXTURES
- ❖ CORRECTION OF SIZES OF ESV SEAL RING-15 DEG. Vs 25 DEG.
- ❖ REMOVAL OF CENTER GUIDE KEYS & ECCENTRIC BUSHES IN BOTTOM CASING
- ❖ REPAIR OF SPRING SUPPORTS
- ❖ CORRECTION OF ALIGNMENT OF PIPING
- ❖ CLEANING OF LUBE OIL-[Bar Chart](#)



## **Lessons Learnt:**

Workshop facilities required during revamp to be recorded and suitable workshop to be located in advance. All machining jobs required to be done to be listed down and procedures to be framed.

Suitable Piping Team for carrying out alteration in Steam piping, consisting of skilled piping fitters and the IBR certified welders to be kept ready. Decision in this regard to be taken at the appropriate time in order to save time loss due to decision making.

# Lessons Learnt:

New set of Spring Supports may be kept available

***Pre revamp meetings to be held between core team who has been assigned the revamp project from customer side as well as the OEM side.***

Availability of Spares required during revamp.

Availability of all special tools and standard tools.

Cleaning of Lubricating Oil well in advance



THANKS